

Effective Date: September 17, 2003

*SPECIFICATIONS

QUALITY: F-400 FOLKLORE

COLORS:	1049 Confetti	1053 Madders	1057 Brushstroke	1061 Picotage
	1050 Cartouche	1054 Fretwork	1058 Airbrush	1062 Ombre
	1051 Arabesque	1055 Foulards	1059 Tapestry	1063 Handkerchief
	1052 Liberty	1056 Challis	1060 Sackcloth	1064 Damask

PILE FIBER	-	100% Antron® Legacy Nylon with Dura Tech Soil Resistance Treatment
YARN PLY	-	2 Ply
TUFTED YARN WEIGHT	-	28 ozs. per sq. yd. (949 g/m ²)
MACHINE GAUGE	-	1/10" (3.94 rows/cm)
STITCHES PER INCH	-	14 (5.51 stitches/cm)
FINISHED PILE THICKNESS	-	.151 inch approx. (3.84 mm)
DENSITY FACTOR	-	6,676
WIDTH	-	12' (3.66m)
PRIMARY BACKING	-	100% Synthetic
SECONDARY BACKING	-	Power Lock® High Performance Backing
PATTERN REPEAT	-	1/2" Wide X 3/4" Long (1.27 cm W x 1.95 cm L)
FLAMMABILITY	-	Flooring Radiant Panel Test ASTM E-648 - Passes - Has an Average Critical Radiant Flux of Greater than .45 watts square centimeter. Class I.
NBS SMOKE CHAMBER	-	(NFDA 258). Has a Maximum Specific Optical Density of 450 or less.

WARRANTIES:

Wear Warranty	-	10 Years
Static Warranty	-	Useful Life
Delamination Guarantee	-	Useful Life
Edge Ravel Guarantee	-	Useful Life
Run Resistance Warranty	-	Useful Life
Recycling	-	Qualifies for the Invista Reclamation Program

CRI INDOOR AIR QUALITY TESTING PROGRAM – PASSES – CERTIFICATION NO. 14222878

NOTES:

Chair pads are recommended under office chairs with roller casters to preserve appearance retention, act as a deterrent toward delamination and to avoid premature or accelerated wear. Clean Step® walk-off tiles by Blue Ridge or walk-off mats are recommended at building entryways to reduce soiling.

*Product specifications are derived from averages resulting from normal manufacturing tolerances in yarn, fiber, fabrication or finishing, and may vary within normal industry tolerances. Construction value quotes are "at point of manufacture". Performance is not affected by these variables.

Due to the nature of patterned textile products, an exact pattern match cannot be guaranteed. Some visual inconsistencies in the surface appearance of all textile products should be expected, including visible seams.

4. Carpet must be installed according to manufacturers carpet installation procedures. Seam sealer must be used.